1. Prepare a USB stick with the following files.

Navn	Status
	Ø
📄 boot.cfg	\odot
FR1902_V83.CML	\odot
FR2002_V83.CML	\odot
SYSFONTTBL	\odot

2. Plug in the USB stick in the USB port of the screen. Connect to voltage.

Press diagonally on the screen within 500ms.

Menu		
Program	Alarm	
Curves	Files	
Storage	Defrosting	
Time	Service	
Log	Set-up	
Graph	Return	

3. Menu appears below.

Press "→".

Alarm		
Alarm		
Files Defrosting Service Set-up		

4. Choose "SD/USB" on menu page 2/3.



5. Press "USBStart".



6. Choose "Download".



7. Choose "Select File".



8. Write down screen size. (TSC1902 vs. TSC2002)

> Choose the correct image for the screen size. (FR1902_Vxx vs. FR2002_Vxx)

Press "Enter".



9. Press "Start".

Download (S	torage->Dis	play)	
Warning:			
Data in the	internal m	emory will b	a lost
Path Name	/FR2002 V	R3 CML	e 1030.
Password n	ot set.		Brating
	Star	t. D	
	U UCAT		
the second strends of the	Color	+ Ello	Pack

10. Press "Yes".



11. When image has been downloaded, press "back".



12. Press "Back".

Download (S	torage->Display)
Warning:	the second second
Uata in the	will be lost
Path Name.	/EP2002 V83 CM
Password p	nt set
1 435901 4 11	
	A REAL PROPERTY AND A REAL
	Start
Contract of the	

13. Press "Exit".



14. Restart by pressing "Yes".

